



RainCrow

Environmental

***Triennial Asbestos
Re-inspection
Report***

**Marshall County Schools
6909 Hwy. 431 S.
Guntersville, AL 35976**

November 16, 2021

Drew Patrick, Asbestos Inspector
752 Myrick Rd., Deatsville, Al. 36022

Cell phone: 334-315-2892

LEA: Marshall County Schools
Central Facilities
6909 Hwy. 431 S.
Guntersville, Al 35976

REINSPECTION DATE: 11/16/2021

INSPECTOR: Drew Patrick

ACCREDITATION NO.: AIN10212B48EAD0

SIGNATURE: *Drew Patrick*

COMMENTS AND INSTRUCTIONS:

All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- There are new building materials at this building. Since a contractor renovated it, and the contractor was aware of the need that no ACBM be utilized in the renovation, a letter from the contractor should be obtained to warrant no asbestos containing materials were used in construction. This letter should be filed in your management plan file. The letter must include this statement:

To the best of my knowledge no asbestos containing building material was used as a building material in (name of the building).

- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

Alabama Asbestos Management Program AHERA Reinspection Form

Date of Previous Inspection – 12-11-18						Date Of Reinspection – 11-16-21					
LEA Name – Marshall County Schools						LEA # 048					
School Name – Central Facilities						School # 000					
Building Name - Central Office						Building # 01					
Address: 6909 Hwy. 431 S. Guntersville, Alabama 35976						Inspector's Name – Drew Patrick					
						Signature - <i>Drew Patrick</i>					
This building has had some renovations since 1988.						Alabama Accreditation No. – AIN10212B48EAD0					

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	144 sq. ft. 2 x 4 Ceiling Tile		250 sq. ft. 2 x 4 Ceiling Tile		1065 sq. ft. 2 x 4 Ceiling Tile		876 sq. ft. 2 x 4 Ceiling Tile		150 sq. ft. 2 x 4 Ceiling Tile		700 sq. ft. 2 x 4 Ceiling Tile		240 sq. ft. 2 x 4 Ceiling Tile		2842 sq. ft. 2 x 4 Ceiling Tile		144 sq. ft. Vinyl Flooring		250 sq. ft. Vinyl Flooring	
		No.	01-08	01-07	01-06	01-05	01-04	01-03	01-02	01-01	02-08	02-07										

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																				
	Surfacing																				
	Miscellaneous		X		X		X		X		X		X		X		X		X		X
	Assumed ACBM																X	X	X	X	
	Sampled/Tested	X		X		X		X		X		X		X		X					
	Non ACBM																				
	ACBM	X		X		X		X		X		X		X		X					
	Nonfriable	X		X		X		X		X		X		X		X		X	X	X	X
Friable																					
Assessment/Reassessment																					
Change in Condition? (Y/N)		N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration	<div style="display: flex; justify-content: space-between;"> <div>Not Listed Originally. Removed In 2012.</div> <div>Not Listed Originally. Removed In 2012.</div> <div>Not Listed Originally. Removed In 2012.</div> <div>Not Listed Originally. Removed In 2012.</div> <div>Not Listed Originally. Removed In 2012.</div> <div>Not Listed Originally. Removed In 2012.</div> <div>Not Listed Originally. Removed In 2012.</div> <div>Not Listed Originally. Removed In 2012.</div> </div>																			
	Physical Damage																				
	Water Damage																				
	Activity/Vibration																				
	Exposure																				
Length of Exposure	Accessibility																				
	1 Hour/Week																				
	5 Hours/Week																				
	10 Hours/Week																				
	20 Hours/Week																				
Check All That Apply	Maintenance																				
	Custodial																				
	Faculty/Students																				
	Public																				
Assessment Category																					

Alabama Asbestos Management Program AHERA Reinspection Form

Date of Previous Inspection – 12-11-18						Date Of Reinspection – 11-16-21					
LEA Name – Marshall County Schools						LEA # 048					
School Name – Central Facilities						School # 000					
Building Name - Central Office						Building # 01					
Address: 6909 Hwy. 431 S. Guntersville, Alabama 35976						Inspector's Name – Drew Patrick					
						Signature - <i>Drew Patrick</i>					
This building has had some renovations since 1988.						Alabama Accreditation No. – AIN10212B48EAD0					

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	240 sq. ft. Vinyl Flooring		360 sq. ft. Wallboard		Sheet Vinyl Floor (Custodial Closet & Strg. Rm) -lt. green pebble pattern)		Sheet Vinyl Floor (Vault) light green pebble pattern)		Sheet Vinyl Floor (Men's RR) mauve pebble pattern)										
			No.																		
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI																				
	Surfacing																				
	Miscellaneous		X		X	X	X	X	X	X	X										
	Assumed ACBM		X		X	X	X	X	X	X	X										
	Sampled/Tested																				
	Non ACBM																				
	ACBM																				
	Nonfriable		X		X	X	X	X	X	X	X										
	Friable																				
Assessment/Reassessment																					
Change in Condition? (Y/N)			Y		N		N		N		Y										
Rate 1 To 5 5 is Worst	Deterioration		Replaced.																		
	Physical Damage																				
	Water Damage																				
	Activity/Vibration																				
	Exposure																				
Length of Exposure	Accessibility			Replaced with new vinyl plank.																	
	1 Hour/Week																				
	5 Hours/Week																				
	10 Hours/Week																				
	20 Hours/Week																				
	40 Hours/Week																				
Check All That Apply	Maintenance				Replaced with new vinyl plank.																
	Custodial																				
	Faculty/Students																				
	Public																				
Assessment Category						Replaced with new vinyl plank.															

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-11-18						Date Of Reinspection – 11-16-21					
LEA Name – Marshall County Schools						LEA # 048					
School Name – Central Facilities						School # 000					
Building Name - Bus Shop						Building # 02					
Address: 6909 Hwy. 431 S. Guntersville, Alabama 35976 This building has had some renovations since 1988.						Inspector's Name – Drew Patrick					
						Signature - <i>Drew Patrick</i>					
						Alabama Accreditation No. – AIN10212B48EAD0					

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	200 sq. ft. Vinyl Flooring		25 sq. ft. Vinyl Flooring		50 sq. ft. Ceiling Tile		200 sq. ft. Ceiling Tile		145 sq. ft. Ceiling Tile											
			No.																			
			02-02		02-01		01-03		01-02		01-01											
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X											
	Assumed ACBM		X		X		X		X		X											
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X		X		X		X		X											
	Friable																					
Assessment/Reassessment																						
Change in Condition? (Y/N)			Y		Y		N		N		N											
Rate 1 To 5 5 is Worst	Deterioration		All Replaced W/ New 12" Vinyl Floor Tile.		All Replaced W/ New 12" Vinyl Floor Tile.		Replaced W/ New Ceiling Tile.		Replaced W/ New Ceiling Tile.		Replaced W/ New Ceiling Tile.											
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility		All Replaced W/ New 12" Vinyl Floor Tile.		All Replaced W/ New 12" Vinyl Floor Tile.		Replaced W/ New Ceiling Tile.		Replaced W/ New Ceiling Tile.		Replaced W/ New Ceiling Tile.											
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week		All Replaced W/ New 12" Vinyl Floor Tile.		All Replaced W/ New 12" Vinyl Floor Tile.		Replaced W/ New Ceiling Tile.		Replaced W/ New Ceiling Tile.		Replaced W/ New Ceiling Tile.											
	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public		All Replaced W/ New 12" Vinyl Floor Tile.		All Replaced W/ New 12" Vinyl Floor Tile.		Replaced W/ New Ceiling Tile.		Replaced W/ New Ceiling Tile.		Replaced W/ New Ceiling Tile.											
Assessment Category																						

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-11-18						Date Of Reinspection – 11-16-21						
LEA Name – Marshall County Schools						LEA # 048						
School Name – Central Facilities						School # 000						
Building Name – Old Day Care (Now Office Building)						Building # 06						
Address: 6909 Hwy. 431 S. Guntersville, Alabama 35976 This building was not listed originally.						Inspector's Name – Drew Patrick						
						Signature - <i>Drew Patrick</i>						
						Alabama Accreditation No. – AIN10212B48EAD0						
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	12" Vinyl Floor Tile	Sheet Vinyl Floor – mauve pattern	Sheet Vinyl Floor – rock pattern	Popcorn Ceiling – 703 sf						
		No.	01-01	02-01	02-02	03-01						
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI											
	Surfacing											
	Miscellaneous											
	Assumed ACBM											
	Sampled/Tested											
	Non ACBM											
	ACBM											
	Nonfriable											
Friable												
Assessment/Reassessment												
Change in Condition? (Y/N)												
Rate 1 To 5 5 is Worst	Deterioration		All Flooring Removed or Covered W/ New Ceramic FT.									
	Physical Damage											
	Water Damage											
	Activity/Vibration											
	Exposure											
Length of Exposure	Accessibility		All Flooring Removed or Covered W/ New Ceramic FT.									
	1 Hour/Week											
	5 Hours/Week											
	10 Hours/Week											
	20 Hours/Week											
Check All That Apply	40 Hours/Week		All Flooring Removed or Covered W/ New Ceramic FT.									
	Maintenance											
	Custodial											
	Faculty/Students											
	Public		Covered W/ New Ceiling Tile.									
Assessment Category												

Drew Patrick, Asbestos Inspector
752 Myrick Rd., Deatsville, Al. 36022

Cell phone: 334-315-2892

LEA: Marshall County Schools
Asbury Jr. HS
1900 Asbury Rd.
Albertville, Al 35950

REINSPECTION DATE: 11/16/2021

INSPECTOR: Drew Patrick

ACCREDITATION NO.: AIN10212B48EAD0

SIGNATURE: *Drew Patrick*

COMMENTS AND INSTRUCTIONS:

All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Old ceiling tiles through-out were determined to be asbestos containing building material (ACBM) and were removed from the hallway in 2012.
- Old ceiling tiles through-out five classrooms were determined to be asbestos containing building material (ACBM) and remain.
- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- There are new building materials at this building. Since a contractor renovated it, and the contractor was aware of the need that no ACBM be utilized in the renovation, a letter from the contractor should be obtained to warrant no asbestos containing materials were used in construction. This letter should be filed in your management plan file. The letter must include this statement:

**To the best of my knowledge no asbestos containing building material
was used as a building material in (name of the building).**

- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

Alabama Asbestos Management Program AHERA Reinspection Form

Date of Previous Inspection – 12-11-18						Date Of Reinspection – 11-16-21					
LEA Name – Marshall County Schools						LEA # 048					
School Name – Asbury JHS (Now Asbury HS)						School # 030					
Building Name - Main						Building # 01					
Address: 1990 Asbury Rd. Albertville, Alabama 35950						Inspector's Name – Drew Patrick					
						Signature - <i>Drew Patrick</i>					
This building has had some renovations since 1988.						Alabama Accreditation No. – AIN10212B48EAD0					

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	170 sq. ft. 2 x 4 Ceiling Tile		8440 sq. ft. 2 x 4 Ceiling Tile		30 sq. ft. 2 x 4 Ceiling Tile		80 sq. ft. 2 x 4 Ceiling Tile		1100 sq. ft. 2 x 4 Ceiling Tile		1660 sq. ft. 2 x 4 Ceiling Tile		180 sq. ft. 2 x 4 Ceiling Tile		640 sq. ft. 2 x 4 Ceiling Tile		500 sq. ft. 2 x 4 Ceiling Tile		960 sq. ft. 2 x 4 Ceiling Tile			
			No.																					
			01-06		01-01		01-10		01-09		01-08		01-07		01-05		01-04		01-03		01-02			
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now		
Check one	TSI																							
	Surfacing																							
	Miscellaneous		X		X		X		X		X		X		X		X		X		X			
	Assumed ACM																							
	Sampled/Tested		X		X		X		X		X		X		X		X		X		X			
	Non ACM																							
	ACBM		X		X	X	X	X	X	X	X		X	X	X	X	X	X	X	X	X			
	Friable		X		X	X	X	X	X	X	X		X	X	X	X	X	X	X	X	X			
Assessment/Reassessment																								
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N		N			
Rate 1 To 5 5 is Worst	Deterioration		Removed In Dec. 2012.		All Remains Except For 4 Classrooms.																			
	Physical Damage																							
	Water Damage																							
	Activity/Vibration																							
	Exposure																							
Length of Exposure	Accessibility		Removed In Dec. 2012.		All Remains Except For 4 Classrooms.																			
	1 Hour/Week																							
	5 Hours/Week																							
	10 Hours/Week																							
	20 Hours/Week																							
Check All That Apply	40 Hours/Week		Removed In Dec. 2012.		All Remains Except For 4 Classrooms.																			
	Maintenance																							
	Custodial																							
		Faculty/Students		Removed In Dec. 2012.		All Remains Except For 4 Classrooms.																		
		Public																						
Assessment Category																								

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-11-18										Date Of Reinspection – 11-16-21									
LEA Name – Marshall County Schools										LEA # 048									
School Name – Asbury JHS (Now Asbury HS)										School # 030									
Building Name - Main										Building # 01									
Address: 1990 Asbury Rd. Albertville, Alabama 35950										Inspector's Name – Drew Patrick									
										Signature - <i>Drew Patrick</i>									
This building has had some renovations since 1988.										Alabama Accreditation No. – AIN10212B48EAD0									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	50 sq. ft. Floor Tile		1980 sq. ft. Floor Tile Off White W/ Green Streaks		50 sq. ft. Floor Tile		270 sq. ft. Floor Tile		80 sq. ft. Floor Tile		30 sq. ft. Floor Tile		1500 sq. ft. Floor Tile		7 sq. ft. Transite Panels		40 sq. ft. Transite Panels		18 sq. ft. Transite Panels	
			No.																			
		No.	02-06		02-02		02-05		02-03		02-09		02-10		02-07		03-11		03-02		03-06	
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM		X	X	X	X	X	X	X	X	X	X	X	X	X		X	X	X	X	X	X
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X	X	X	X	X	X	X	X	X	X	X	X	X		X	X	X	X	X	X
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
	Assessment Category																					

These Tiles Were Removed During 2007 Renovations.

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-11-18					Date Of Reinspection – 11-16-21									
LEA Name – Marshall County Schools					LEA # 048									
School Name – Asbury JHS (Now Asbury HS)					School # 030									
Building Name - Main					Building # 01									
Address: 1990 Asbury Rd. Albertville, Alabama 35950					Inspector's Name – Drew Patrick									
					Signature - <i>Drew Patrick</i>									
This building has had some renovations since 1988.					Alabama Accreditation No. – AIN10212B48EAD0									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	9" VFT (Classrooms) Cream W/ Grey Streaks 7187 sf																
		No.	02-01																

Inspection/Reinspection																				
-------------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

Check one	TSI																			
	Surfacing																			
	Miscellaneous	X																		
	Assumed ACBM	X	X																	
	Sampled/Tested																			
	Non ACBM																			
	ACBM																			
	Nonfriable	X	X																	
	Friable																			

Assessment/Reassessment																				
-------------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

Change in Condition? (Y/N)			N																	
----------------------------	--	--	---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			

Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
	40 Hours/Week																			

Check All That Apply	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			

Assessment Category																				
---------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-11-18										Date Of Reinspection – 11-16-21									
LEA Name – Marshall County Schools										LEA # 048									
School Name – Asbury JHS (Now Asbury HS)										School # 030									
Building Name - Main										Building # 01									
Address: 1990 Asbury Rd. Albertville, Alabama 35950										Inspector's Name – Drew Patrick									
										Signature - <i>Drew Patrick</i>									
This building has had some renovations since 1988.										Alabama Accreditation No. – AIN10212B48EAD0									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	25 sq. ft. Transite Panels		220 sq. ft. Transite Panels		20 sq. ft. Transite Panels		75 sq. ft. Transite Panels		265 sq. ft. Transite Panels		100 sq. ft. Transite Panels		25 sq. ft. Transite Panels		350 sq. ft. Transite Panels		1200 sq. ft. Wallboard		4 – Sinks W/ Gray Spray-on Material (West Wing Classrooms)	
			No.																			
		No.	03-03		03-01		03-07		04-15		04-14		04-13		04-12		04-11		05-11		06-01	
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																					X
	Miscellaneous		X		X		X		X		X		X		X		X		X			
	Assumed ACBM		X	X	X	X	X	X	X		X		X		X		X		X		X	X
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X	X	X	X	X	X	X		X		X		X		X		X		X	X
	Friable																					
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
	Assessment Category																					

These Panels Were Removed During 2007 Renovations.	These Panels Were Removed During 2007 Renovations.	These Panels Were Removed During 2007 Renovations.	These Panels Were Removed During 2007 Renovations.	These Panels Were Removed During 2007 Renovations.	These Panels Were Removed in Approx. 2005.	This Material Is Not Listed in The Original Management Plan.
--	--	--	--	--	--	--

Drew Patrick, Asbestos Inspector
752 Myrick Rd., Deatsville, Al. 36022

Cell phone: 334-315-2892

LEA: Marshall County Schools
Claysville JHS
140 Claysville School Rd.
Guntersville, Al 35976

REINSPECTION DATE: 11/16/2021

INSPECTOR: Drew Patrick

ACCREDITATION NO.: AIN10212B48EAD0

SIGNATURE: *Drew Patrick*

COMMENTS AND INSTRUCTIONS:

All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- There are new building materials at this building. Since a contractor renovated it, and the contractor was aware of the need that no ACBM be utilized in the renovation, a letter from the contractor should be obtained to warrant no asbestos containing materials were used in construction. This letter should be filed in your management plan file. The letter must include this statement:

To the best of my knowledge no asbestos containing building material was used as a building material in (name of the building).

- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

Alabama Asbestos Management Program AHERA Reinspection Form

Date of Previous Inspection – 12-12-18										Date Of Reinspection – 11-16-21									
LEA Name – Marshall County Schools										LEA # 048									
School Name – Claysville JHS (Now Claysville School)										School # 70									
Building Name - Main Building										Building # 01									
Address: 140 Claysville School Rd. Guntersville, Alabama 35976										Inspector's Name – Drew Patrick									
										Signature - <i>Drew Patrick</i>									
										Alabama Accreditation No. – AIN10212B48EAD0									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	5020 sq. ft. Ceiling Tile		602 sq. ft. Ceiling Tile		30 sq. ft. Plaster		240 sq. ft. Ceiling Tile		880 sq. ft. Floor Tile		500 sq. ft. Floor Tile		30 sq. ft. Floor Tile		400 sq. ft. Ceiling Tile		Sheet Vinyl Floor (Downstairs CR) It brn pebble pattern. 680 sq																			
			No.																																			
		No.	01-01		01-02		04-12		05-15		06-11		06-13		07-14		08-09		09-16																			
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now																		
Check one	TSI																																					
	Surfacing						X																															
	Miscellaneous		X		X				X		X		X		X		X																					
	Assumed ACM		X		X				X		X		X		X		X																					
	Sampled/Tested						X																															
	Non ACM						X																															
	ACBM																																					
	Nonfriable		X		X		X		X		X		X		X		X																					
Friable																																						
Assessment/Reassessment																																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		Y																			
Rate 1 To 5 5 is Worst	Deterioration																																					
	Physical Damage																																					
	Water Damage																																					
	Activity/Vibration																																					
	Exposure																																					
Length of Exposure	Accessibility																																					
	1 Hour/Week																																					
	5 Hours/Week																																					
	10 Hours/Week																																					
	20 Hours/Week																																					
Check All That Apply	40 Hours/Week																																					
	Maintenance																																					
	Custodial																																					
	Faculty/Students																																					
	Public																																					
Assessment Category			Replaced W/ New Ceiling Tile In 1991.		Replaced W/ New Ceiling Tile In 1991.				Replaced W/ New Ceiling Tile In 1991.		Removed During 1991 Renovations.		Replaced W/ New Floor Tile In 1991.		Replaced W/ Ceramic FT		Replaced W/ New Ceiling Tile In 1991.		<div style="display: flex; justify-content: space-between;"> 1 2 </div> <div style="display: flex; justify-content: space-between;"> 1 1 </div> <div style="display: flex; justify-content: space-between;"> X X </div> <div style="display: flex; justify-content: space-between;"> X X </div> <div style="display: flex; justify-content: space-between;"> X X </div> <div style="display: flex; justify-content: space-between;"> 5 </div>		All Removed.																	

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-12-18										Date Of Reinspection – 11-16-21												
LEA Name – Marshall County Schools										LEA # 048												
School Name – Claysville JHS (Now Claysville School)										School # 70												
Building Name - Gym										Building # 02												
Address: 140 Claysville School Rd. Guntersville, Alabama 35976										Inspector's Name – Drew Patrick												
										Signature - <i>Drew Patrick</i>												
										Alabama Accreditation No. – AIN10212B48EAD0												
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	310 sq. ft. Floor Tile (Concession Stand)		1320 sq. ft. Floor Tile (Locker Rooms)		375 sq. ft. Floor Tile (Front Restrooms)		120 sq. ft. Floor Tile		675 sq. ft. Floor Tile (Lobby)		1480 sq. ft. Floor Tile (Court Area)		1345 sq. ft. Transite Ceiling Tile (Boys & Girls Locker Rooms)		120 sq. ft. Transite Ceiling Tile		70 sq. ft. Transite Ceiling Tile		90 sq. ft. Ceiling Tile	
			No.	01-01	01-02	01-03	01-04	01-05	01-06	02-02	02-04	02-07	03-01									
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now		
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X			
	Assumed ACBM		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X		
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X		
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N			
Rate 1 To 5 5 is Worst	Deterioration		Covered W/ New 12" Vinyl Floor Tile Except For Closet.		Replaced Or Covered W/ New 12" Vinyl Floor Tile.		Covered W/ New 12" Vinyl Floor Tile.		Covered W/ New 12" Vinyl Floor Tile.		Covered W/ New 12" Vinyl Floor Tile.		Replaced Or Covered W/ New 12" Vinyl Floor Tile.		Boys Locker Room Replaced W/ New 2x2 Ceiling Tile.		Replaced W/ New 2x2 Ceiling Tile.		Replaced W/ New 2x2 Ceiling Tile.		Replaced W/ New 2x2 Ceiling Tile.	
Length of Exposure	Accessibility		Covered W/ New 12" Vinyl Floor Tile Except For Closet.		Replaced Or Covered W/ New 12" Vinyl Floor Tile.		Covered W/ New 12" Vinyl Floor Tile.		Covered W/ New 12" Vinyl Floor Tile.		Covered W/ New 12" Vinyl Floor Tile.		Replaced Or Covered W/ New 12" Vinyl Floor Tile.		Boys Locker Room Replaced W/ New 2x2 Ceiling Tile.		Replaced W/ New 2x2 Ceiling Tile.		Replaced W/ New 2x2 Ceiling Tile.		Replaced W/ New 2x2 Ceiling Tile.	
Check All That Apply	Maintenance		Covered W/ New 12" Vinyl Floor Tile Except For Closet.		Replaced Or Covered W/ New 12" Vinyl Floor Tile.		Covered W/ New 12" Vinyl Floor Tile.		Covered W/ New 12" Vinyl Floor Tile.		Covered W/ New 12" Vinyl Floor Tile.		Replaced Or Covered W/ New 12" Vinyl Floor Tile.		Boys Locker Room Replaced W/ New 2x2 Ceiling Tile.		Replaced W/ New 2x2 Ceiling Tile.		Replaced W/ New 2x2 Ceiling Tile.		Replaced W/ New 2x2 Ceiling Tile.	
Assessment Category																						

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-12-18					Date Of Reinspection – 11-16-21				
LEA Name – Marshall County Schools					LEA # 048				
School Name – Claysville JHS (Now Claysville School)					School # 70				
Building Name - Gym					Building # 02				
Address: 140 Claysville School Rd. Guntersville, Alabama 35976					Inspector's Name – Drew Patrick				
					Signature - <i>Drew Patrick</i>				
					Alabama Accreditation No. – AIN10212B48EAD0				

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	675 sq. ft. Ceiling Tile (Lobby Area)	100 sq. ft. Floor Tile (Locker Rooms RR's)	2 – “ Modine” Gas Ceiling Heaters/ Lining (Court Area)												
		No.	03-05	04-08	05-06												

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																		
	Surfacing																		
	Miscellaneous		X		X		X												
	Assumed ACBM	X		X	X	X	X												
	Sampled/Tested																		
	Non ACBM																		
	ACBM																		
	Nonfriable	X		X	X	X	X												
Friable																			
Assessment/Reassessment																			
Change in Condition? (Y/N)		N		N		N													
Rate 1 To 5 5 is Worst	Deterioration																		
	Physical Damage																		
	Water Damage																		
	Activity/Vibration																		
	Exposure																		
Length of Exposure	Accessibility																		
	1 Hour/Week																		
	5 Hours/Week																		
	10 Hours/Week																		
	20 Hours/Week																		
Check All That Apply	40 Hours/Week																		
	Maintenance																		
	Custodial																		
	Faculty/Students																		
	Public																		
	Assessment Category																		

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-12-18					Date Of Reinspection – 11-16-21				
LEA Name – Marshall County Schools					LEA # 048				
School Name – Claysville JHS (Now Claysville School)					School # 70				
Building Name - Lunchroom					Building # 03				
Address: 140 Claysville School Rd. Guntersville, Alabama 35976					Inspector's Name – Drew Patrick				
					Signature - <i>Drew Patrick</i>				
					Alabama Accreditation No. – AIN10212B48EAD0				

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2000 sq. ft. Ceiling Tile (Cafe Area)		2000 sq. ft. Floor Tile (Cafe Area)		175 sq. ft. Ceiling Tile (Kitchen Area)		325 sq. ft. Ceiling Tile (Kitchen Area)		30 sq. ft. Ceiling Tile (Kitchen Area)		50 sq. ft. Ceiling Tile (Kitchen Area)									
			No.																			
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X									
	Assumed ACBM		X		X	X	X		X		X		X									
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X		X	X	X		X		X		X									
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N									
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						

Alabama Asbestos Management Program AHERA Reinspection Form

Date of Previous Inspection – 12-12-18						Date Of Reinspection – 11-16-21					
LEA Name – Marshall County Schools						LEA # 048					
School Name – Claysville JHS (Now Claysville School)						School # 70					
Building Name - Science Building						Building # 04					
Address: 140 Claysville School Rd. Guntersville, Alabama 35976						Inspector's Name – Drew Patrick					
						Signature - <i>Drew Patrick</i>					
						Alabama Accreditation No. – AIN10212B48EAD0					
This building has been totally renovated.											

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	1480 sq. ft. Ceiling Tile		50 sq. ft. Ceiling Tile		50 sq. ft. Ceiling Tile		280 sq. ft. Floor Tile		50 sq. ft. Floor Tile		50 sq. ft. Floor Tile		1280 sq. ft. Wallboard		120 sq. ft. Wallboard		120 sq. ft. Wallboard	
			No.																	
		No.	01-01		01-02		01-03		02-01		02-02		02-03		03-01		03-02		03-03	
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing																			
	Miscellaneous		X		X		X		X		X		X		X		X		X	
	Assumed ACM		X		X		X		X		X		X		X		X		X	
	Sampled/Tested																			
	Non ACM																			
	ACBM																			
	Nonfriable		X		X		X		X		X		X		X		X		X	
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
Check All That Apply	40 Hours/Week																			
	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
	Assessment Category																			

Alabama Asbestos Management Program AHERA Reinspection Form

Date of Previous Inspection – 12-12-18										Date Of Reinspection – 11-16-21										
LEA Name – Marshall County Schools										LEA # 048										
School Name – Claysville JHS (Now Claysville School)										School # 70										
Building Name - Portable Classroom										Building # 07										
Address: 140 Claysville School Rd. Guntersville, Alabama 35976 This building has been removed since 1989.										Inspector's Name – Drew Patrick										
										Signature - <i>Drew Patrick</i>										
										Alabama Accreditation No. – AIN10212B48EAD0										
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description																		
			No.																	
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing																			
	Miscellaneous																			
	Assumed ACBM																			
	Sampled/Tested																			
	Non ACBM																			
	ACBM																			
	Nonfriable																			
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)																				
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
Check All That Apply	40 Hours/Week																			
	Maintenance																			
	Custodial																			
	Faculty/Students																			
Public																				
Assessment Category																				

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-12-18										Date Of Reinspection – 11-16-21										
LEA Name – Marshall County Schools										LEA # 048										
School Name – Claysville JHS (Now Claysville School)										School # 70										
Building Name - Portable Classroom										Building # 08										
Address: 140 Claysville School Rd. Guntersville, Alabama 35976 This building has been removed since 1989.										Inspector's Name – Drew Patrick										
										Signature - <i>Drew Patrick</i>										
										Alabama Accreditation No. – AIN10212B48EAD0										
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description																		
			No.																	
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing																			
	Miscellaneous																			
	Assumed ACBM																			
	Sampled/Tested																			
	Non ACBM																			
	ACBM																			
	Nonfriable																			
	Friable																			
Assessment/Reassessment																				
Change in Condition? (Y/N)																				
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
	40 Hours/Week																			
Check All That Apply	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
Assessment Category																				

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-12-18										Date Of Reinspection – 11-16-21										
LEA Name – Marshall County Schools										LEA # 048										
School Name – Claysville JHS (Now Claysville School)										School # 70										
Building Name - Trailer										Building # 09										
Address: 140 Claysville School Rd. Guntersville, Alabama 35976 This building has been removed since 1989.										Inspector's Name – Drew Patrick										
										Signature - <i>Drew Patrick</i>										
										Alabama Accreditation No. – AIN10212B48EAD0										
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description																		
		No.																		
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing																			
	Miscellaneous																			
	Assumed ACBM																			
	Sampled/Tested																			
	Non ACBM																			
	ACBM																			
	Nonfriable																			
	Friable																			
Assessment/Reassessment																				
Change in Condition? (Y/N)																				
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
Check All That Apply	40 Hours/Week																			
	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
	Assessment Category																			

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-12-18										Date Of Reinspection – 11-16-21										
LEA Name – Marshall County Schools										LEA # 048										
School Name – Claysville JHS (Now Claysville School)										School # 70										
Building Name - Trailer										Building # 10										
Address: 140 Claysville School Rd. Guntersville, Alabama 35976 This building has been removed since 1989.										Inspector's Name – Drew Patrick										
										Signature - <i>Drew Patrick</i>										
										Alabama Accreditation No. – AIN10212B48EAD0										
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description																		
		No.																		
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing																			
	Miscellaneous																			
	Assumed ACBM																			
	Sampled/Tested																			
	Non ACBM																			
	ACBM																			
	Nonfriable																			
	Friable																			
Assessment/Reassessment																				
Change in Condition? (Y/N)																				
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
	40 Hours/Week																			
Check All That Apply	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
Assessment Category																				

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-12-18										Date Of Reinspection – 11-16-21										
LEA Name – Marshall County Schools										LEA # 048										
School Name – Claysville JHS (Now Claysville School)										School # 70										
Building Name - Portable Classroom										Building # 13										
Address: 140 Claysville School Rd. Guntersville, Alabama 35976 This building has been removed since 1989.										Inspector's Name – Drew Patrick										
										Signature - <i>Drew Patrick</i>										
										Alabama Accreditation No. – AIN10212B48EAD0										
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description																		
			No.																	
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing																			
	Miscellaneous																			
	Assumed ACBM																			
	Sampled/Tested																			
	Non ACBM																			
	ACBM																			
	Nonfriable																			
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)																				
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
Check All That Apply	40 Hours/Week																			
	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
	Assessment Category																			

Drew Patrick, Asbestos Inspector
752 Myrick Rd., Deatsville, Al. 36022

Cell phone: 334-315-2892

LEA: Marshall County Schools
Douglas Elementary School
Hwy. 75
Douglas, Al 35964

REINSPECTION DATE: 11/16/2021

INSPECTOR: Drew Patrick

ACCREDITATION NO.: AIN10212B48EAD0

SIGNATURE: Drew Patrick

COMMENTS AND INSTRUCTIONS:

All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- There are new building materials at this building. Since a contractor renovated it, and the contractor was aware of the need that no ACBM be utilized in the renovation, a letter from the contractor should be obtained to warrant no asbestos containing materials were used in construction. This letter should be filed in your management plan file. The letter must include this statement:

To the best of my knowledge no asbestos containing building material was used as a building material in (name of the building).

- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-11-18										Date Of Reinspection – 11-16-21									
LEA Name – Marshall County Schools										LEA # 048									
School Name – Douglas Elementary School										School # 90									
Building Name - Main Building										Building # 01									
Address: Hwy. 75 Douglas, Alabama 35964										Inspector's Name – Drew Patrick									
										Signature - <i>Drew Patrick</i>									
										Alabama Accreditation No. – AIN10212B48EAD0									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	690 sq. ft. Ceiling Tile		490 sq. ft. Ceiling Tile		160 sq. ft. Ceiling Tile		250 sq. ft. Ceiling Tile		150 sq. ft. Ceiling Tile		1500 sq. ft. Ceiling Tile		9000 sq. ft. Ceiling Tile		150 sq. ft. Ceiling Tile		4500 sq. ft. Wallboard Ceiling		800 sq. ft. Wallboard Ceiling	
			No.																			
		No.	01-01		01-02		01-03		01-04		01-05		01-06		01-07		01-08		02-09		02-10	
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM		X		X		X		X		X		X		X		X		X	X	X	X
	Sampled/Tested																					
	Non ACBM			X		X		X		X		X		X		X		X				
	ACBM																					
	Nonfriable		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
40 Hours/Week																						
Check All That Apply	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						

Alabama Asbestos Management Program AHERA Reinspection Form

Date of Previous Inspection – 12-11-18						Date Of Reinspection – 11-16-21					
LEA Name – Marshall County Schools						LEA # 048					
School Name – Douglas Elementary School						School # 90					
Building Name - Main Building						Building # 01					
Address: Hwy. 75 Douglas, Alabama 35964						Inspector's Name – Drew Patrick					
						Signature - <i>Drew Patrick</i>					
						Alabama Accreditation No. – AIN10212B48EAD0					

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	75 sq. ft. Plaster	Sinks W/ Spray-on Material (Throughout)	Fire doors (Thru Out Classrooms)												
		No.	03-11	04-02	05-09												

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																		
	Surfacing	X		X															
	Miscellaneous					X													
	Assumed ACBM	X	X	X	X	X	X												
	Sampled/Tested																		
	Non ACBM																		
	ACBM																		
	Nonfriable	X	X	X	X	X	X												
Friable																			
Assessment/Reassessment																			
Change in Condition? (Y/N)		N		N		N													
Rate 1 To 5 5 is Worst	Deterioration			Not Listed in The Original Management Plan.	Not Listed in The Original Management Plan.														
	Physical Damage																		
	Water Damage																		
	Activity/Vibration																		
	Exposure																		
Length of Exposure	Accessibility																		
	1 Hour/Week																		
	5 Hours/Week																		
	10 Hours/Week																		
	20 Hours/Week																		
Check All That Apply	40 Hours/Week																		
	Maintenance																		
	Custodial																		
	Faculty/Students																		
	Public																		
	Assessment Category																		

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-11-18					Date Of Reinspection – 11-16-21				
LEA Name – Marshall County Schools					LEA # 048				
School Name – Douglas Elementary School					School # 90				
Building Name - Classroom Building					Building # 02				
Address: Hwy. 75 Douglas, Alabama 35964					Inspector's Name – Drew Patrick				
					Signature - <i>Drew Patrick</i>				
This building was renovated in the 2000's.					Alabama Accreditation No. – AIN10212B48EAD0				

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2000 sq. ft. Ceiling Tile		200 sq. ft. Ceiling Tile		160 sq. ft. Ceiling Tile		250 sq. ft. Ceiling Tile		25 sq. ft. Transite Ceiling Tile		1800 sq. ft. Ceiling Tile		1800 sq. ft. Floor Tile		150 sq. ft. Transite Panels					
			No.																			
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X					
	Assumed ACM		X		X		X		X		X	X	X		X	X	X	X				
	Sampled/Tested																					
	Non ACM																					
	ACBM																					
	Nonfriable		X		X		X		X		X	X	X		X	X	X	X				
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N					
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						

Alabama Asbestos Management Program AHERA Reinspection Form

Date of Previous Inspection – 12-11-18						Date Of Reinspection – 11-16-21																
LEA Name – Marshall County Schools						LEA # 048																
School Name – Douglas Elementary School						School # 90																
Building Name – Lunchroom (NowLibrary)						Building # 03																
Address: Hwy. 75 Douglas, Alabama 35964 This building was renovated in the 1991 with the removal of most suspect ACBM.						Inspector's Name – Drew Patrick																
						Signature - <i>Drew Patrick</i>																
						Alabama Accreditation No. – AIN10212B48EAD0																
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	250 sq. ft. Plaster		1000 sq. ft. Wallboard		100 sq. ft. Transite ceiling Tile		2450 sq. ft. Floor Tile		210 sq. ft. Floor Tile		Window Caulking (SE exterior windows)									
		No.	01-01	02-02	03-02	04-03	05-03	06														
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now		
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X									
	Assumed ACBM		X		X		X		X	X	X	X	X		X							
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X		X		X		X	X	X	X		X								
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		Y									
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
	40 Hours/Week																					
Check All That Apply	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						

Covered W/ New Commercial Carpet During Renovations.

Covered W/ New Commercial Carpet During Renovations.

Drew Patrick, Asbestos Inspector
752 Myrick Rd., Deatsville, Al. 36022

Cell phone: 334-315-2892

LEA: Marshall County Schools
Douglas High School
225 Eagle Dr.
Douglas, Al 35964

REINSPECTION DATE: 11/16/2021

INSPECTOR: Drew Patrick

ACCREDITATION NO.: AIN10212B48EAD0

SIGNATURE: *Drew Patrick*

COMMENTS AND INSTRUCTIONS:

All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- There are new building materials at this building. Since a contractor renovated it, and the contractor was aware of the need that no ACBM be utilized in the renovation, a letter from the contractor should be obtained to warrant no asbestos containing materials were used in construction. This letter should be filed in your management plan file. The letter must include this statement:

To the best of my knowledge no asbestos containing building material was used as a building material in (name of the building).

- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

Alabama Asbestos Management Program AHERA Reinspection Form

Date of Previous Inspection – 12-11-18										Date Of Reinspection – 11-16-21									
LEA Name – Marshall County Schools										LEA # 048									
School Name – Douglas High School										School # 100									
Building Name - Main										Building # 01									
Address: 225 Eagle Drive Douglas, Alabama 35964										Inspector's Name – Drew Patrick									
										Signature - <i>Drew Patrick</i>									
This building has had some renovations since 1988.										Alabama Accreditation No. – AIN10212B48EAD0									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	6825 sq. ft. Floor Tile (Halls/classrooms? Orange)		490 sq. ft. Floor Tile		2550 sq. ft. Floor Tile (library, asst. princ. office? Now lt gray/black)		290 sq. ft. Floor Tile (ramp or breezeway entrance?)		2850 sq. ft. Floor Tile (lab and end classroom?)		384 sq. ft. Floor Tile (Library office?)		100 sq. ft. Floor Tile		6825 sq. ft. Ceiling Tile		490 sq. ft. Ceiling Tile		2550 sq. ft. Ceiling Tile	
			No.																			
		No.	01-01		01-02		01-03		01-04		01-05		01-06		01-08		02-01		02-02		02-03	
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM		X	X	X	X	X	X	X	X	X	X	X	X	X		X		X		X	
	Sampled/Tested																	X		X		X
	Non ACBM																	X		X		X
	ACBM																					
	Nonfriable		X	X	X	X	X	X	X	X	X	X	X	X	X		X	X	X	X	X	X
	Friable																					
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
	Assessment Category																					

These Tiles Were Removed During Recent Renovations.

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-11-18										Date Of Reinspection – 11-16-21									
LEA Name – Marshall County Schools										LEA # 048									
School Name – Douglas High School										School # 100									
Building Name - Main										Building # 01									
Address: 225 Eagle Drive Douglas, Alabama 35964										Inspector's Name – Drew Patrick									
										Signature - <i>Drew Patrick</i>									
This building has had some renovations since 1988.										Alabama Accreditation No. – AIN10212B48EAD0									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	290 sq. ft. Ceiling Tile		2850 sq. ft. Ceiling Tile		384 sq. ft. Ceiling Tile		120 sq. ft. Ceiling Tile		2160 sq. ft. Ceiling Tile		70 sq. ft. Ceiling Tile		610 sq. ft. Ceiling Tile		350 sq. ft. Ceiling Tile		130 sq. ft. Plaster		1300 sq. ft. Ceiling Tile	
			No.																			
		No.	02-04		02-05		02-06		02-07		02-08		02-09		02-10		02-11		03-04		04-12	
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X	X	X	X
	Assumed ACBM		X		X		X		X		X		X		X		X		X	X	X	X
	Sampled/Tested			X		X		X		X		X		X		X		X				
	Non ACBM			X		X		X		X		X		X		X		X				
	ACBM																					
	Nonfriable		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
	40 Hours/Week																					
Check All That Apply	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-11-18						Date Of Reinspection – 11-16-21												
LEA Name – Marshall County Schools						LEA # 048												
School Name – Douglas High School						School # 100												
Building Name - Main						Building # 01												
Address: 225 Eagle Drive Douglas, Alabama 35964						Inspector's Name – Drew Patrick												
						Signature - <i>Drew Patrick</i>												
						Alabama Accreditation No. – AIN10212B48EAD0												
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	140 sq. ft. Transite Ceiling Tile		Sheetrock Walls (Through-out)		Sheetrock Ceiling (Downstairs Storage Adj. Freezer)		87 sq. ft. Sheet Vinyl Floor (Teacher Workroom, Closet &)		Cove Base Mastic Thru Out Halls and CRs							
			No.	05-13	06-01	07-01	08-01	09-01										
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																	
	Surfacing																	
	Miscellaneous		X		X		X		X		X							
	Assumed ACBM		X	X	X	X	X	X		X	X							
	Sampled/Tested								X									
	Non ACBM								X									
	ACBM																	
	Nonfriable		X	X	X	X	X	X	X	X	X	X						
	Friable																	
Assessment/Reassessment																		
Change in Condition? (Y/N)			N		N		N		Y		N							
Rate 1 To 5 5 is Worst	Deterioration				Not Listed in The Original Management Plan.				Not Listed in The Original Management Plan.									
	Physical Damage																	
	Water Damage																	
	Activity/Vibration																	
	Exposure																	
Length of Exposure	Accessibility				Not Listed in The Original Management Plan.				Not Listed in The Original Management Plan.									
	1 Hour/Week																	
	5 Hours/Week																	
	10 Hours/Week																	
	20 Hours/Week																	
Check All That Apply	40 Hours/Week				Not Listed in The Original Management Plan.				Not Listed in The Original Management Plan.									
	Maintenance																	
	Custodial																	
	Faculty/Students																	
	Public																	
Assessment Category																		

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-11-18										Date Of Reinspection – 11-16-21									
LEA Name – Marshall County Schools										LEA # 048									
School Name – Douglas High School										School # 100									
Building Name - Gym										Building # 02									
Address: 225 Eagle Drive Douglas, Alabama 35964										Inspector's Name – Drew Patrick									
										Signature - <i>Drew Patrick</i>									
										Alabama Accreditation No. – AIN10212B48EAD0									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	1440 sq. ft. Ceiling Tile		310 sq. ft. Ceiling Tile		210 sq. ft. Ceiling Tile		504 sq. ft. Ceiling Tile		1440 sq. ft. Floor Tile		210 sq. ft. Floor Tile		230 sq. ft. Floor Tile		500 sq. ft. Floor Tile		875 sq. ft. Floor Tile		70 sq. ft. Wallboard	
			No.																			
		No.	01-02		01-03		01-04		01-07		02-02		02-04		02-06		02-07		02-08		03-02	
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM		X		X		X		X		X		X		X		X		X		X	
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X		X		X		X		X		X		X		X		X		X	
	Friable																					
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		Y		N	
Rate 1 To 5 is Worst	Deterioration		<div style="display: flex; justify-content: space-between;"> <div>Replaced W/ New 2x2 Ceiling Tile.</div> <div>Replaced W/ New 2x2 Ceiling Tile.</div> <div>Replaced W/ New 2x2 Ceiling Tile.</div> <div>Replaced W/ New 2x2 Ceiling Tile.</div> <div>Covered Or Replaced W/ New</div> <div>Covered Or Replaced W/ New</div> <div>Some Covered W/ Hardwood Covered Or Replaced W/ New</div> <div>Replaced w/ Rubber Mats.</div> <div>All Covered W/ Hardwood and Replaced W/ New 12" VFT.</div> <div>Did Not Find.</div> </div>																			
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
Public																						
Assessment Category																						

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-11-18						Date Of Reinspection – 11-16-21										
LEA Name – Marshall County Schools						LEA # 048										
School Name – Douglas High School						School # 100										
Building Name - Gym						Building # 02										
Address: 225 Eagle Drive Douglas, Alabama 35964						Inspector's Name – Drew Patrick										
						Signature - <i>Drew Patrick</i>										
						Alabama Accreditation No. – AIN10212B48EAD0										
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	630 sq. ft. Wallboard	500 sq. ft. Plaster	4 – Gas Ceiling Heaters	4 – Fire-doors										
		No.	03-05	04-01	05-04	06-04										
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI															
	Surfacing				X											
	Miscellaneous		X				X		X							
	Assumed ACBM		X		X	X	X		X	X						
	Sampled/Tested															
	Non ACBM															
	ACBM															
	Nonfriable		X		X	X	X		X	X						
	Friable															
Assessment/Reassessment																
Change in Condition? (Y/N)			N		N		Y		N							
Rate 1 To 5 5 is Worst	Deterioration															
	Physical Damage															
	Water Damage															
	Activity/Vibration															
	Exposure															
Length of Exposure	Accessibility															
	1 Hour/Week															
	5 Hours/Week															
	10 Hours/Week															
	20 Hours/Week															
Check All That Apply	40 Hours/Week															
	Maintenance															
	Custodial															
	Faculty/Students															
	Public															
Assessment Category			Removed During Renovations		Did Not Find.		All removed.									

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-11-18					Date Of Reinspection – 11-16-21												
LEA Name – Marshall County Schools					LEA # 048												
School Name – Douglas High School					School # 100												
Building Name - Field House					Building # 03												
Address: 225 Eagle Drive Douglas, Alabama 35964					Inspector's Name – Drew Patrick												
					Signature - <i>Drew Patrick</i>												
					Alabama Accreditation No. – AIN10212B48EAD0												
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	120 sq. ft. Ceiling Tile														
				No.	01-01												
Inspection/Reinspection				Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																
	Surfacing																
	Miscellaneous			X													
	Assumed ACBM																
	Sampled/Tested																
	Non ACBM			X													
	ACBM																
	Nonfriable			X													
Friable																	
Assessment/Reassessment																	
Change in Condition? (Y/N)				N													
Rate 1 To 5 5 is Worst	Deterioration																
	Physical Damage																
	Water Damage																
	Activity/Vibration																
	Exposure																
Length of Exposure	Accessibility																
	1 Hour/Week																
	5 Hours/Week																
	10 Hours/Week																
	20 Hours/Week																
Check All That Apply	40 Hours/Week																
	Maintenance																
	Custodial																
	Faculty/Students																
	Public																
	Assessment Category																

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-11-18						Date Of Reinspection – 11-16-21																	
LEA Name – Marshall County Schools						LEA # 048																	
School Name – Douglas High School						School # 100																	
Building Name - Vocational Building						Building # 04																	
Address: 225 Eagle Drive Douglas, Alabama 35964						Inspector's Name – Drew Patrick																	
						Signature - <i>Drew Patrick</i>																	
						Alabama Accreditation No. – AIN10212B48EAD0																	
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	120 sq. ft. Ceiling Tile		25 sq. ft. Ceiling Tile		100 sq. ft. Ceiling Tile		540 sq. ft. Ceiling Tile (Agri-Business Classroom)		120 sq. ft. Sheet Flooring		250 sq. ft. Sheet Flooring		540 sq. ft. Sheet Flooring (Agri-Business Classroom)		700 sq. ft. Sheet Flooring		5- Sinks W/ White Spray-on Material		Reznor Gas Ceiling Heater Lining (Ag. Shop)		
			No.	01-01	01-02	01-03	01-04	02-01	02-03	02-04	03-05	04-05	05-06										
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI																					X	
	Surfacing																						
	Miscellaneous		X		X		X		X		X		X		X								
	Assumed ACBM		X		X		X		X	X	X		X		X	X	X	X	X	X		X	
	Sampled/Tested										X		X		X								
	Non ACBM										X		X		X								
	ACBM																						
	Nonfriable		X		X		X		X	X	X	X		X	X	X	X	X	X	X		X	
	Friable																						
Assessment/Reassessment																							
Change in Condition? (Y/N)			N		N		N		N		Y		Y		Y		N		N		Y		
Rate 1 To 5 5 is Worst	Deterioration																						
	Physical Damage																						
	Water Damage																						
	Activity/Vibration																						
	Exposure																						
Length of Exposure	Accessibility																						
	1 Hour/Week																						
	5 Hours/Week																						
	10 Hours/Week																						
	20 Hours/Week																						
Check All That Apply	40 Hours/Week																						
	Maintenance																						
	Custodial																						
	Faculty/Students																						
	Public																						
Assessment Category																							
			<div>Replaced During Renovation</div> <div>Replaced During Renovation</div> <div>Replaced During Renovation</div> <div>Covered W/ New 2x2 Ceiling Tile.</div> <div>Covered W/ New Sheet Vinyl Floor</div> <div>Covered W/ New Sheet Vinyl Floor</div> <div>Covered W/ New Sheet Vinyl Flooring.</div> <div>Covered W/ New Light Brown Rock Pattern Sheet Vinyl</div> <div>Not Listed in The Original Management Plan.</div>																				

Drew Patrick, Asbestos Inspector
752 Myrick Rd., Deatsville, Al. 36022

Cell phone: 334-315-2892

LEA: Marshall County Schools
Grassy Jr. High School
2233 Shoal Creek Rd.
Arab, Al 35016

REINSPECTION DATE: 11/16/2021

INSPECTOR: Drew Patrick

ACCREDITATION NO.: AIN10212B48EAD0

SIGNATURE: *Drew Patrick*

COMMENTS AND INSTRUCTIONS:

All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- There are new building materials at this building. Since a contractor renovated it, and the contractor was aware of the need that no ACBM be utilized in the renovation, a letter from the contractor should be obtained to warrant no asbestos containing materials were used in construction. This letter should be filed in your management plan file. The letter must include this statement:

To the best of my knowledge no asbestos containing building material was used as a building material in (name of the building).

- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-12-18						Date Of Reinspection – 11-16-21						
LEA Name – Marshall County Schools						LEA # 048						
School Name – Grassy JHS (Now Brindlee Mt. Elem.)						School # 120						
Building Name - Main Building						Building # 01						
Address: 2233 Shoal Creek Rd. Arab, Alabama 35016 This building has had some renovations since 1992.						Inspector's Name – Drew Patrick						
						Signature - <i>Drew Patrick</i>						
						Alabama Accreditation No. – AIN10212B48EAD0						
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	12,200 sq. ft. Floor Tile	730 sq. ft. Floor Tile	354 sq. ft. Floor Tile	1700 sq. ft. Floor Tile	1500 sq. ft. Floor Tile	300 sq. ft. Floor Tile	1250 sq. ft. Floor Tile	360 sq. ft. Floor Tile	2350 sq. ft. Plastered Wallboard	288 sq. ft. Plastered Wallboard
		No.	01-01	01-02	01-03	01-04	01-05	01-06	01-07	01-08	02-01	02-08
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI											
	Surfacing										X	X
	Miscellaneous		X	X	X	X	X	X	X	X		
	Assumed ACBM		X	X	X	X	X	X	X	X	X	X
	Sampled/Tested											
	Non ACBM											
	ACBM											
	Nonfriable		X	X	X	X	X	X	X	X	X	X
	Friable											
Assessment/Reassessment												
Change in Condition? (Y/N)			N	N	N	N	N	N	N	N	N	
Rate 1 To 5 5 is Worst	Deterioration		Most Covered W/ New Commercial Carpet. Most Removed and Replaced W/ New 12" VFT									
	Physical Damage											
	Water Damage											
	Activity/Vibration											
	Exposure											
Length of Exposure	Accessibility		Replaced W/ New Laminate Floor.									
	1 Hour/Week											
	5 Hours/Week											
	10 Hours/Week											
	20 Hours/Week											
Check All That Apply	40 Hours/Week		Replaced W/ New VCT Floor.									
	Maintenance											
	Custodial											
	Faculty/Students											
	Public		Replaced W/ New VCT Floor. Storage Area Is Carpeted.									
Assessment Category												
			Sheetrock Covers all Walls.									

Alabama Asbestos Management Program AHERA Reinspection Form

Date of Previous Inspection – 12-12-18					Date Of Reinspection – 11-16-21				
LEA Name – Marshall County Schools					LEA # 048				
School Name – Grassy JHS (Now Brindlee Mt. Elem.)					School # 120				
Building Name - Main Building					Building # 01				
Address: 2233 Shoal Creek Rd. Arab, Alabama 35016					Inspector's Name – Drew Patrick				
					Signature - <i>Drew Patrick</i>				
This building has had some renovations since 1992.					Alabama Accreditation No. – AIN10212B48EAD0				

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	570 sq. ft. Sheet Flooring		2160 sq. ft. Textured Wallboard Ceiling															
			No.																	
			03-02		04-04															

Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing				X															
	Miscellaneous		X																	
	Assumed ACBM				X	X														
	Sampled/Tested	X																		
	Non ACBM	X	X																	
	ACBM																			
	Nonfriable	X	X	X	X															
	Friable																			
Assessment/Reassessment																				
Change in Condition? (Y/N)		N		N																
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
Check All That Apply	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
Assessment Category																				

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-12-18						Date Of Reinspection – 11-16-21						
LEA Name – Marshall County Schools						LEA # 048						
School Name – Grassy JHS (Now Brindlee Mt. Elem.)						School # 120						
Building Name - Gym						Building # 02						
Address: 2233 Shoal Creek Rd. Arab, Alabama 35016 The suspect materials in this building were removed during renovations.						Inspector's Name – Drew Patrick						
						Signature - <i>Drew Patrick</i>						
						Alabama Accreditation No. – AIN10212B48EAD0						
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	288 sq. ft. Ceiling Tile	150 sq. ft. Ceiling Tile	625 sq. ft. Ceiling Tile	150 sq. ft. Floor Tile	625 sq. ft. Floor Tile	Gas Ceiling Heater Lining (Gym Stage)				
		No.	01-01	01-02	01-03	02-02	02-03	03				
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI							X				
	Surfacing											
	Miscellaneous	X		X		X		X				
	Assumed ACBM	X		X		X		X				
	Sampled/Tested											
	Non ACBM											
	ACBM											
	Nonfriable	X		X		X		X		X		
Friable												
Assessment/Reassessment												
Change in Condition? (Y/N)			N		N		N		N		Y	
Rate 1 To 5 5 is Worst	Deterioration											
	Physical Damage											
	Water Damage											
	Activity/Vibration											
	Exposure											
Length of Exposure	Accessibility											
	1 Hour/Week											
	5 Hours/Week											
	10 Hours/Week											
	20 Hours/Week											
Check All That Apply	Maintenance											
	Custodial											
	Faculty/Students											
	Public											
Assessment Category												

Drew Patrick, Asbestos Inspector
752 Myrick Rd., Deatsville, Al. 36022

Cell phone: 334-315-2892

LEA: Marshall County Schools
DAR High School
6077 Main St.
Grant, Al 35747

REINSPECTION DATE: 11/16/2021

INSPECTOR: Drew Patrick

ACCREDITATION NO.: AIN10212B48EAD0

SIGNATURE: *Drew Patrick*

COMMENTS AND INSTRUCTIONS:

All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- There are new building materials at this building. Since a contractor renovated it, and the contractor was aware of the need that no ACBM be utilized in the renovation, a letter from the contractor should be obtained to warrant no asbestos containing materials were used in construction. This letter should be filed in your management plan file. The letter must include this statement:

To the best of my knowledge no asbestos containing building material was used as a building material in (name of the building).

- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-12-18										Date Of Reinspection – 11-16-21												
LEA Name – Marshall County Schools										LEA # 048												
School Name – DAR High School										School # 140												
Building Name - Seimes Thomas Building										Building # 01												
Address: 6077 Main St. Grant, Alabama 35747										Inspector's Name – Drew Patrick												
										Signature - <i>Drew Patrick</i>												
										Alabama Accreditation No. – AIN10212B48EAD0												
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	9300 sq. ft. Ceiling Tile		2140 sq. ft. Ceiling Tile		4000 sq. ft. Ceiling Tile		1400 sq. ft. Ceiling Tile		3150 sq. ft. Ceiling Tile		160 sq. ft. Ceiling Tile		9300 sq. ft. Floor Tile		1940 sq. ft. Sheet Vinyl Floor– tan pebble pattern		160 sq. ft. Floor Tile Ceiling		30 sq. ft. Floor Tile Ceiling	
			No.	01-01	01-02	01-04	01-06	01-07	01-08	02-01	02-02	02-08	02-09									
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM		X		X		X		X		X		X		X		X		X		X	
	Sampled/Tested			X		X				X		X										
	Non ACBM			X		X				X		X										
	ACBM																					
	Nonfriable		X	X	X	X	X		X		X	X	X	X	X	X	X	X	X	X	X	X
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
Public																						
Assessment Category																						

Alabama Asbestos Management Program AHERA Reinspection Form

Date of Previous Inspection – 12-12-18										Date Of Reinspection – 11-16-21												
LEA Name – Marshall County Schools										LEA # 048												
School Name – DAR High School										School # 140												
Building Name - Seimes Thomas Building										Building # 01												
Address: 6077 Main St. Grant, Alabama 35747										Inspector's Name – Drew Patrick												
										Signature - <i>Drew Patrick</i>												
										Alabama Accreditation No. – AIN10212B48EAD0												
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	5000 sq. ft. Plaster (Hall Walls)		1070 sq. ft. Plaster (Restrooms)		435 sq. ft. Wallboard		30 sq. ft. Wallboard		585 sq. ft. Transite Ceiling Tile		30 sq. ft. Transite Panels		35 sq. ft. Transite Panels		100 sq. ft. Plaster		Transite Lining (Science Lab Chemical Fume Hood)		1 – Sink W/ White Spray-on Material (Lab CR Chemical Fume Hood)	
		No.	03-04	03-05	04-05	04-09	05-03	06-04	06-06	07-02	08-01	09-01										
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing		X		X										X						X	
	Miscellaneous						X		X		X		X		X				X			
	Assumed ACBM		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		Y		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
	40 Hours/Week																					
Check All That Apply	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						

Alabama Asbestos Management Program AHERA Reinspection Form

Date of Previous Inspection – 12-12-18										Date Of Reinspection – 11-16-21									
LEA Name – Marshall County Schools										LEA # 048									
School Name – DAR High School										School # 140									
Building Name - Seimes Thomas Building										Building # 01									
Address: 6077 Main St. Grant, Alabama 35747										Inspector's Name – Drew Patrick									
										Signature - <i>Drew Patrick</i>									
										Alabama Accreditation No. – AIN10212B48EAD0									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2 – Sinks W/ Gray Spray-on Material (Classroom #15 & Library Kitchen)																
		No.	09-02																

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																		
	Surfacing	X																	
	Miscellaneous																		
	Assumed ACBM	X	X																
	Sampled/Tested																		
	Non ACBM																		
	ACBM																		
	Nonfriable	X	X																
Friable																			
Assessment/Reassessment																			
Change in Condition? (Y/N)		N																	
Rate 1 To 5 5 is Worst	Deterioration																		
	Physical Damage																		
	Water Damage																		
	Activity/Vibration																		
	Exposure																		
Length of Exposure	Accessibility																		
	1 Hour/Week																		
	5 Hours/Week																		
	10 Hours/Week																		
	20 Hours/Week																		
Check All That Apply	40 Hours/Week																		
	Maintenance																		
	Custodial																		
	Faculty/Students																		
	Public																		
	Assessment Category																		

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-12-18						Date Of Reinspection – 11-16-21																
LEA Name – Marshall County Schools						LEA # 048																
School Name – DAR High School						School # 140																
Building Name - Home Economics Building (Now MS Office)						Building # 02																
Address: 6077 Main St. Grant, Alabama 35747						Inspector's Name – Drew Patrick																
						Signature - <i>Drew Patrick</i>																
						Alabama Accreditation No. – AIN10212B48EAD0																
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	225 sq. ft. Ceiling Tile		1800 sq. ft. Ceiling Tile		80 sq. ft. Ceiling Tile		6800 sq. ft. Ceiling Tile		720 sq. ft. Ceiling Tile		200 sq. ft. Ceiling Tile		50 sq. ft. Ceiling Tile		2600 sq. ft. Ceiling Tile		200 sq. ft. Ceiling Tile		170 sq. ft. Sheet Flooring	
		No.	01-01	01-03	01-04	01-06	01-07	01-08	01-10	01-11	01-12	02-02										
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now		
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X			
	Assumed ACBM		X	X	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X		
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X	X	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X		
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N			
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-12-18										Date Of Reinspection – 11-16-21												
LEA Name – Marshall County Schools										LEA # 048												
School Name – DAR High School										School # 140												
Building Name - Home Economics Building (Now MS Office)										Building # 02												
Address: 6077 Main St. Grant, Alabama 35747										Inspector's Name – Drew Patrick												
										Signature - <i>Drew Patrick</i>												
										Alabama Accreditation No. – AIN10212B48EAD0												
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	300 sq. ft. Sheet Flooring		80 sq. ft. Sheet Flooring		300 sq. ft. Sheet Flooring		4000 sq. ft. Sheet Flooring		200 sq. ft. Sheet Flooring		2600 sq. ft. Sheet Flooring		400 sq. ft. Floor Tile – olive green w/ cream marbled		55 sq. ft. Floor Tile		1500 sq. ft. Floor Tile		100 sq. ft. Floor Tile	
			No.	02-03	02-04	02-05	02-06	02-08	02-11	03-01	03-02	03-03	03-09									
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM		X	X	X	X	X	X			X	X	X	X	X	X	X	X	X		X	X
	Sampled/Tested								X													
	Non ACBM																					
	ACBM								X	X												
	Nonfriable		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X		X	X
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
40 Hours/Week																						
Check All That Apply	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						

Med. Brown Pebble Pattern


Covered W/ New 12" VCT

Replaced W/ New Terrazzo Floor.

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-12-18										Date Of Reinspection – 11-16-21										
LEA Name – Marshall County Schools										LEA # 048										
School Name – DAR High School										School # 140										
Building Name - Home Economics Building (Now MS Office)										Building # 02										
Address: 6077 Main St. Grant, Alabama 35747										Inspector's Name – Drew Patrick										
										Signature - <i>Drew Patrick</i>										
										Alabama Accreditation No. – AIN10212B48EAD0										
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	50 sq. ft. Floor Tile		200 sq. ft. Floor Tile		400 sq. ft. Vinyl coated Sheetrock		300 sq. ft. Vinyl coated Sheetrock		100 sq. ft. Vinyl coated Sheetrock		240 sq. ft. Wallboard		Sheetrock Wall Board (Upstairs Classrooms)		7 LF / Vinyl Expansion Joint (Basement Mech. Room)			
			No.	03-10	03-12	04-01	04-05	04-09	05-03	05-06	06-01									
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing																			
	Miscellaneous		X		X		X		X		X		X		X					
	Assumed ACBM		X	X	X	X	X		X		X		X	X	X	X	X			
	Sampled/Tested																			
	Non ACBM							X		X		X								
	ACBM																			
	Nonfriable		X	X	X	X	X		X		X		X	X	X	X	X	X		
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)			N		N		N		N		N		N		N					
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
40 Hours/Week																				
Check All That Apply	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
Assessment Category																				

Alabama Asbestos Management Program AHERA Reinspection Form
--

Date of Previous Inspection – 12-12-18	Date Of Reinspection – 11-16-21
LEA Name – Marshall County Schools	LEA # 048
School Name – DAR High School	School # 140
Building Name - Ag. Building	Building # 03
Address: 6077 Main St. Grant, Alabama 35747	Inspector's Name – Drew Patrick
	Signature - 
	Alabama Accreditation No. – AIN10212B48EAD0

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	200 sq. ft. Floor Tile	80 sq. ft. Floor Tile	1000 sq. ft. Ceiling Tile	100 sq. ft. Ceiling Tile	100 sq. ft. Ceiling Tile	100 sq. ft. Wallboard	80 sq. ft. Wallboard	1000 sq. ft. Floor Tile	100 sq. ft. Floor Tile	Old Window Caulk (Through-out Upstairs & Basement)
		No.	01-02	01-03	02-01	02-02	02-04	03-02	03-03	04-01	04-04	05-01

[illegible][illegible][illegible]

Change in Condition? (Y/N)	Y	N	Y	Y	Y	N	N	N	N	N
----------------------------	---	---	---	---	---	---	---	---	---	---

[illegible]

Alabama Asbestos Management Program AHERA Reinspection Form

Date of Previous Inspection – 12-12-18						Date Of Reinspection – 11-16-21					
LEA Name – Marshall County Schools						LEA # 048					
School Name – DAR High School						School # 140					
Building Name - New Gym						Building # 04					
Address: 6077 Main St. Grant, Alabama 35747						Inspector's Name – Drew Patrick					
						Signature - <i>Drew Patrick</i>					
						Alabama Accreditation No. – AIN10212B48EAD0					

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	48 sq. ft. Transite Panels	1350 sq. ft. Floor Tile	240 sq. ft. Floor Tile	500 sq. ft. Floor Tile						
		No.	01-01	02-02	02-03	02-04						

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																		
	Surfacing																		
	Miscellaneous		X		X		X		X										
	Assumed ACBM	X		X	X	X	X	X	X										
	Sampled/Tested																		
	Non ACBM																		
	ACBM																		
	Nonfriable	X		X	X	X	X	X	X										
Friable																			
Assessment/Reassessment																			
Change in Condition? (Y/N)		N		N		N		Y											
Rate 1 To 5 5 is Worst	Deterioration																		
	Physical Damage																		
	Water Damage																		
	Activity/Vibration																		
	Exposure																		
Length of Exposure	Accessibility																		
	1 Hour/Week																		
	5 Hours/Week																		
	10 Hours/Week																		
	20 Hours/Week																		
Check All That Apply	Maintenance																		
	Custodial																		
	Faculty/Students																		
	Public																		
Assessment Category																			

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-12-18					Date Of Reinspection – 11-16-21				
LEA Name – Marshall County Schools					LEA # 048				
School Name – DAR High School					School # 140				
Building Name - Old Gym					Building # 05				
Address: 6077 Main St. Grant, Alabama 35747					Inspector's Name – Drew Patrick				
					Signature - <i>Drew Patrick</i>				
					Alabama Accreditation No. – AIN10212B48EAD0				

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	1200 sq. ft. Wallboard	Sheet Vinyl Floor (Upstairs Storage) Light Tan - 108 sq. ft.															
		No.	01-01	02-01															

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI																			
	Surfacing				X															
	Miscellaneous		X																	
	Assumed ACBM	X	X	X	X															
	Sampled/Tested																			
	Non ACBM																			
	ACBM																			
	Nonfriable	X	X	X	X															
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)		N		N																
Rate 1 To 5 5 is Worst	Deterioration			Not Listed in The Original Management Plan.																
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
Check All That Apply	40 Hours/Week																			
	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
	Assessment Category																			

Alabama Asbestos Management Program AHERA Reinspection Form

Date of Previous Inspection – 12-12-18						Date Of Reinspection – 11-16-21					
LEA Name – Marshall County Schools						LEA # 048					
School Name – DAR High School						School # 140					
Building Name - Lunchroom						Building # 06					
Address: 6077 Main St. Grant, Alabama 35747 This building was renovated in 1994 with installation of new walls & lay-in ceiling tiles covering old ceiling.						Inspector's Name – Drew Patrick					
						Signature - <i>Drew Patrick</i>					
						Alabama Accreditation No. – AIN10212B48EAD0					

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2850 sq. ft. Ceiling Tile		1000 sq. ft. Wallboard		60 sq. ft. Wallboard		270 sq. ft. Wallboard		600 sq. ft. Wallboard		85 sq. ft. Wallboard		190 sq. ft. Wallboard		40 sq. ft. Plaster		300 sq. ft. Plaster		320 sq. ft. Plaster	
			No.																			
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																X		X		X	
	Miscellaneous		X		X		X		X		X		X		X							
	Assumed ACM		X		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
	Sampled/Tested																					
	Non ACM																					
	ACBM																					
	Nonfriable		X		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-12-18					Date Of Reinspection – 11-16-21													
LEA Name – Marshall County Schools					LEA # 048													
School Name – DAR High School					School # 140													
Building Name - Lunchroom					Building # 06													
Address: 6077 Main St. Grant, Alabama 35747 This building was renovated in 1994 with installation of new walls & lay-in ceiling tiles covering old ceiling.					Inspector's Name – Drew Patrick													
					Signature - <i>Drew Patrick</i>													
					Alabama Accreditation No. – AIN10212B48EAD0													
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Air-cell Pipe Insulation (Basement Water Heater Room)															
		No.	05-01															
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI		X															
	Surfacing																	
	Miscellaneous																	
	Assumed ACBM		X	X														
	Sampled/Tested																	
	Non ACBM																	
	ACBM																	
	Nonfriable																	
Friable		X	X															
Assessment/Reassessment																		
Change in Condition? (Y/N)			N															
Rate 1 To 5 5 is Worst	Deterioration																	
	Physical Damage																	
	Water Damage																	
	Activity/Vibration																	
	Exposure																	
Length of Exposure	Accessibility																	
	1 Hour/Week																	
	5 Hours/Week																	
	10 Hours/Week																	
	20 Hours/Week																	
	40 Hours/Week																	
Check All That Apply	Maintenance																	
	Custodial																	
	Faculty/Students																	
	Public																	
Assessment Category																		

Drew Patrick, Asbestos Inspector
752 Myrick Rd., Deatsville, Al. 36022

Cell phone: 334-315-2892

LEA: Marshall County Schools
DAR Elementary School
6077 Main St.
Grant, Al 35747

REINSPECTION DATE: 11/16/2021

INSPECTOR: Drew Patrick

ACCREDITATION NO.: AIN10212B48EAD0

SIGNATURE: *Drew Patrick*

COMMENTS AND INSTRUCTIONS:

All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- There are new building materials at this building. Since a contractor renovated it, and the contractor was aware of the need that no ACBM be utilized in the renovation, a letter from the contractor should be obtained to warrant no asbestos containing materials were used in construction. This letter should be filed in your management plan file. The letter must include this statement:

To the best of my knowledge no asbestos containing building material was used as a building material in (name of the building).

- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-12-18						Date Of Reinspection – 11-16-21					
LEA Name – Marshall County Schools						LEA # 048					
School Name – DAR Elementary						School # 145					
Building Name - Main (Jacob's Building)						Building # 01					
Address: 6077 Main St. Grant, Alabama 35747						Inspector's Name – Drew Patrick					
						Signature - <i>Drew Patrick</i>					
						Alabama Accreditation No. – AIN10212B48EAD0					

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	6800 sq. ft. Ceiling Tile		100 sq. ft. Ceiling Tile		380 sq. ft. Ceiling Tile		400 sq. ft. Ceiling Tile		4500 sq. ft. Ceiling Tile		220 sq. ft. Ceiling Tile		200 sq. ft. Ceiling Tile		150 sq. ft. Ceiling Tile		500 sq. ft. Ceiling Tile		150 sq. ft. Ceiling Tile	
			No.																			
		No.	01-01		01-02		01-04		01-06		01-07		01-08		01-09		01-10		01-11		01-12	
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM		X		X		X		X		X		X		X		X		X		X	
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X		X		X		X		X		X		X		X		X		X	
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration		Identified As “ Armstrong” Non-Asbestos Ceiling Tile.																			
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility		Identified As “ Armstrong” Non-Asbestos Ceiling Tile.																			
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week		Identified As “ Armstrong” Non-Asbestos Ceiling Tile.																			
	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category			Identified As “ Armstrong” Non-Asbestos Ceiling Tile.																			

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-12-18										Date Of Reinspection – 11-16-21									
LEA Name – Marshall County Schools										LEA # 048									
School Name – DAR Elementary										School # 145									
Building Name - Main (Jacob's Building)										Building # 01									
Address: 6077 Main St. Grant, Alabama 35747										Inspector's Name – Drew Patrick									
										Signature - <i>Drew Patrick</i>									
										Alabama Accreditation No. – AIN10212B48EAD0									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2850 sq. ft. Ceiling Tile (Auditorium)		8500 sq. ft. Wallboard		1700 sq. ft. Wallboard		1400 sq. ft. Wallboard		700 sq. ft. Wallboard		500 sq. ft. Wallboard		100 sq. ft. Wallboard		1000 sq. ft. Wallboard		150 sq. ft. Floor Tile (Visitors RR) Burnt Orange - 84 sf		550 sq. ft. Floor Tile (Blue Grayed Marbled)	
			No.																			
		No.	01-13		02-01		02-03		02-04		02-06		02-08		02-09		02-11		03-03		03-07	
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM		X		X		X		X		X		X	X	X	X	X	X	X	X	X	X
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X		X		X		X		X		X	X	X	X	X	X	X	X	X	X
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category			Replaced W/ New Ceiling Tile. Determined To Be Plywood Walls. Determined To Be Plywood Walls. Determined To Be Plywood Walls. Determined To Be Plywood Walls. Most Halls Covered W/ Commercial Carpet. Front Hall covered w/ vinyl plank due to water leak.																			

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-12-18										Date Of Reinspection – 11-16-21												
LEA Name – Marshall County Schools										LEA # 048												
School Name – DAR Elementary										School # 145												
Building Name - Main (Jacob's Building)										Building # 01												
Address: 6077 Main St. Grant, Alabama 35747										Inspector's Name – Drew Patrick												
										Signature - <i>Drew Patrick</i>												
										Alabama Accreditation No. – AIN10212B48EAD0												
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	200 sq. ft. Floor Tile		200 sq. ft. Plaster (Old Vault)		150 sq. ft. Plastered Wallboard (Wall & Ceiling)		50 sq. ft. Plastered Wallboard		190 sq. ft. Floor Tile (9" VAT)		900 sq. ft. Plaster		2400 sq. ft. Sheet Flooring (Auditorium)		1 Sink W/ Black Spray-on (Old Health Room)		128 sq. ft. - 12" Vinyl Floor Tile (Each End & Back / Stage) med. brown		55 sq. ft. - 12" Vinyl Floor Tile (Closet) med. Brown marbled	
			No.	03-09	04-05	05-03	05-07	06-04	07-04	08-13	09-09	03-11	03-12									
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing				X		X		X			X				X						
	Miscellaneous		X								X				X				X			X
	Assumed ACBM		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		Y		Y	
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
Public																						
Assessment Category			Tile Removed Except in Restroom. Covered W/ Wood.																			
			Replaced W/ New Hardwood Floor.																			
			Not Listed in The Original Management Plan.																			
			Not Listed in The Original Management Plan.																			
			Not Listed in The Original Management Plan.																			

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-12-18						Date Of Reinspection – 11-16-21																
LEA Name – Marshall County Schools						LEA # 048																
School Name – DAR Elementary						School # 145																
Building Name - Classroom Building (Primary)						Building # 02																
Address: 6077 Main St. Grant, Alabama 35747 This building was renovated in 1990.						Inspector's Name – Drew Patrick																
						Signature - <i>Drew Patrick</i>																
						Alabama Accreditation No. – AIN10212B48EAD0																
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2500 sq. ft. Ceiling Tile		1350 sq. ft. Ceiling Tile		2000 sq. ft. Floor Tile		180 sq. ft. Wallboard Ceiling		500 sq. ft. Floor Tile		500 sq. ft. Floor Tile		180 sq. ft. Floor Tile		2000 sq. ft. Ceiling Tile		2000 sq. ft. Floor Tile		500 sq. ft. Ceiling Tile	
			No.	01-01	01-05	02-01	03-04	04-01	04-03	04-04	05-02	06-02	07-03									
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now		
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X			
	Assumed ACBM		X		X		X		X	X	X		X		X		X		X			
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X		X		X		X	X	X		X		X		X		X			
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N			
Rate 1 To 5 5 is Worst	Deterioration		Replaced W/ New 2x4 Ceiling Tile.		Replaced W/ New 2x4 Ceiling Tile.		Replaced Or Covered W/ New 12" Vinyl Floor Tile.				Replaced Or Covered W/ New 12" Vinyl Floor Tile.		Replaced Or Covered W/ New 12" Vinyl Floor Tile.		Replaced Or Covered W/ New 12" Vinyl Floor Tile.		Replaced W/ New 2x4 Ceiling Tile.		Replaced Or Covered W/ New 12" Vinyl Floor Tile.		Replaced W/ New 2x4 Ceiling Tile.	
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility		Replaced W/ New 2x4 Ceiling Tile.		Replaced W/ New 2x4 Ceiling Tile.		Replaced Or Covered W/ New 12" Vinyl Floor Tile.				Replaced Or Covered W/ New 12" Vinyl Floor Tile.		Replaced Or Covered W/ New 12" Vinyl Floor Tile.		Replaced Or Covered W/ New 12" Vinyl Floor Tile.		Replaced W/ New 2x4 Ceiling Tile.		Replaced Or Covered W/ New 12" Vinyl Floor Tile.		Replaced W/ New 2x4 Ceiling Tile.	
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	Maintenance		Replaced W/ New 2x4 Ceiling Tile.		Replaced W/ New 2x4 Ceiling Tile.		Replaced Or Covered W/ New 12" Vinyl Floor Tile.				Replaced Or Covered W/ New 12" Vinyl Floor Tile.		Replaced Or Covered W/ New 12" Vinyl Floor Tile.		Replaced Or Covered W/ New 12" Vinyl Floor Tile.		Replaced W/ New 2x4 Ceiling Tile.		Replaced Or Covered W/ New 12" Vinyl Floor Tile.		Replaced W/ New 2x4 Ceiling Tile.	
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-12-18						Date Of Reinspection – 11-16-21					
LEA Name – Marshall County Schools						LEA # 048					
School Name – DAR Elementary						School # 145					
Building Name - Jacob's Building (Now Privett Library)						Building # 03					
Address: 6077 Main St. Grant, Alabama 35747						Inspector's Name – Drew Patrick					
						Signature - <i>Drew Patrick</i>					
This building was the old Main Building / Music Building.						Alabama Accreditation No. – AIN10212B48EAD0					

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	450 sq. ft. Ceiling Tile		80 sq. ft. Ceiling Tile		80 sq. ft. Ceiling Tile		1850 sq. ft. Ceiling Tile		25 sq. ft. Ceiling Tile		2000 sq. ft. Ceiling Tile		800 sq. ft. Wallboard		200 sq. ft. Wallboard		1500 sq. ft. Wallboard		100 sq. ft. Wallboard	
			No.																			
			01-01		01-02		01-03		01-04		01-05		01-06		02-01		02-02		02-04		02-05	
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM		X		X		X		X		X		X		X		X		X		X	
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X		X		X		X		X		X		X		X		X		X	
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						

Alabama Asbestos Management Program AHERA Reinspection Form

Date of Previous Inspection – 12-12-18										Date Of Reinspection – 11-16-21									
LEA Name – Marshall County Schools										LEA # 048									
School Name – DAR Elementary										School # 145									
Building Name - Jacob's Building (Now Privett Library)										Building # 03									
Address: 6077 Main St. Grant, Alabama 35747										Inspector's Name – Drew Patrick									
										Signature - <i>Drew Patrick</i>									
This building was the old Main Building / Music Building.										Alabama Accreditation No. – AIN10212B48EAD0									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	1400 sq. ft. Wallboard																
		No.	02-06																

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																		
	Surfacing																		
	Miscellaneous	X																	
	Assumed ACBM	X																	
	Sampled/Tested																		
	Non ACBM																		
	ACBM																		
	Nonfriable	X																	
Friable																			
Assessment/Reassessment																			
Change in Condition? (Y/N)		N																	
Rate 1 To 5 5 is Worst	Deterioration																		
	Physical Damage																		
	Water Damage																		
	Activity/Vibration																		
	Exposure																		
Length of Exposure	Accessibility																		
	1 Hour/Week																		
	5 Hours/Week																		
	10 Hours/Week																		
	20 Hours/Week																		
	40 Hours/Week																		
Check All That Apply	Maintenance																		
	Custodial																		
	Faculty/Students																		
	Public																		
Assessment Category																			

Drew Patrick, Asbestos Inspector
752 Myrick Rd., Deatsville, Al. 36022

Cell phone: 334-315-2892

LEA: Marshall County Schools
Union Grove Jr. High School
3685 Union Grove Rd.
Union Grove, Al 35175

REINSPECTION DATE: 11/16/2021

INSPECTOR: Drew Patrick

ACCREDITATION NO.: AIN10212B48EAD0

SIGNATURE: *Drew Patrick*

COMMENTS AND INSTRUCTIONS:

A tornado destroyed this school. It is no longer in use.

- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

Drew Patrick, Asbestos Inspector
752 Myrick Rd., Deatsville, Al. 36022

Cell phone: 334-315-2892

LEA: Marshall County Schools
Marshall County Tech School
12312 US Hwy. 431 S.
Guntersville, Al 35976

REINSPECTION DATE: 11/16/2021

INSPECTOR: Drew Patrick

ACCREDITATION NO.: AIN10212B48EAD0

SIGNATURE: Drew Patrick

COMMENTS AND INSTRUCTIONS:

All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Old ceiling tiles through-out the main hall have been determined to be asbestos containing building material (ACBM) and should be removed.
- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- There are new building materials at this building. Since a contractor renovated it, and the contractor was aware of the need that no ACBM be utilized in the renovation, a letter from the contractor should be obtained to warrant no asbestos containing materials were used in construction. This letter should be filed in your management plan file. The letter must include this statement:

To the best of my knowledge no asbestos containing building material was used as a building material in (name of the building).

- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-11-18					Date Of Reinspection – 11-16-21				
LEA Name – Marshal County Schools					LEA # 048				
School Name – Marshall County Tech School					School # 600				
Building Name - Main					Building # 01				
Address: 12312 US Hwy. 431 S. Guntersville, Alabama 35976					Inspector's Name – Drew Patrick				
					Signature - <i>Drew Patrick</i>				
					Alabama Accreditation No. – AIN10212B48EAD0				

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	3826 sq. ft. Ceiling Tile		10420 sq. ft. Ceiling Tile		1230 sq. ft. Ceiling Tile		455 sq. ft. Ceiling Tile		7060 sq. ft. Ceiling Tile		180 sq. ft. Ceiling Tile		2500 sq. ft. Ceiling Tile		200 sq. ft. Ceiling Tile		320 sq. ft. Ceiling Tile		2500 sq. ft. Ceiling Tile	
			No.																			
			01-01		01-02		01-03		01-04		01-05		01-06		01-07		01-08		01-09		01-10	
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM		X	X	X		X		X		X		X		X		X		X		X	
	Sampled/Tested										X											
	Non ACBM																					
	ACBM										X											
	Nonfriable		X	X	X		X		X				X		X		X		X		X	
Friable										X												
Assessment/Reassessment											X											
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration		<div style="display: flex; justify-content: space-between;"> <div>Replaced W/ New Ceiling Tile. 120 SF Remains @ Keeling's Office</div> <div>Replaced W/ New Ceiling Tile.</div> <div>Replaced W/ New Ceiling Tile.</div> <div>Replaced W/ New Ceiling Tile.</div> <div>All Removed in 2012</div> <div>Replaced W/ New Ceiling Tile.</div> <div>Replaced W/ New Ceiling Tile.</div> <div>Replaced W/ New Ceiling Tile.</div> <div>Replaced W/ New Ceiling Tile.</div> <div>Replaced W/ New Ceiling Tile.</div> <div>Replaced W/ New Ceiling Tile.</div> </div>																			
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
	40 Hours/Week																					
Check All That Apply	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-11-18						Date Of Reinspection – 11-16-21					
LEA Name – Marshal County Schools						LEA # 048					
School Name – Marshall County Tech School						School # 600					
Building Name - Main						Building # 01					
Address: 12312 US Hwy. 431 S. Guntersville, Alabama 35976						Inspector's Name – Drew Patrick					
						Signature - <i>Drew Patrick</i>					
						Alabama Accreditation No. – AIN10212B48EAD0					

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	100 sq. ft. Ceiling Tile		300 sq. ft. Ceiling Tile		96 sq. ft. Transite Panels		343 sq. ft. Transite Panels		16 sq. ft. Transite Panels		30 sq. ft. Transite Panels		6 sq. ft. Transite Panels		12 sq. ft. Transite Panels		16 sq. ft. Transite Panels		6 sq. ft. Transite Panels			
			No.		01-11		01-12		03-01		03-02		03-05		03-07		03-08		03-09		03-10		03-12	
			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now		
Check one	TSI																							
	Surfacing																							
	Miscellaneous		X		X		X		X		X		X		X		X		X		X			
	Assumed ACBM		X		X		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X		
	Sampled/Tested																							
	Non ACBM																							
	ACBM																							
	Nonfriable		X		X		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X		
Friable																								
Assessment/Reassessment																								
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N					
Rate 1 To 5 5 is Worst	Deterioration																							
	Physical Damage																							
	Water Damage																							
	Activity/Vibration																							
	Exposure																							
Length of Exposure	Accessibility																							
	1 Hour/Week																							
	5 Hours/Week																							
	10 Hours/Week																							
	20 Hours/Week																							
Check All That Apply	40 Hours/Week																							
	Maintenance																							
	Custodial																							
	Faculty/Students																							
	Public																							
	Assessment Category																							

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-11-18										Date Of Reinspection – 11-16-21														
LEA Name – Marshal County Schools										LEA # 048														
School Name – Marshall County Tech School										School # 600														
Building Name - Main										Building # 01														
Address: 12312 US Hwy. 431 S. Guntersville, Alabama 35976										Inspector's Name – Drew Patrick														
										Signature - <i>Drew Patrick</i>														
										Alabama Accreditation No. – AIN10212B48EAD0														
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	36 sq. ft. Transite Panels		18 sq. ft. Transite Panels		36 sq. ft. Transite Panels		280 sq. ft. Sheet Flooring		1100 sq. ft. Sheet Flooring		40 sq. ft. Sheet Flooring		25 sq. ft. Sheet Flooring		30 sq. ft. Sheet Flooring		1245 sq. ft. Wallboard		100 sq. ft. Wallboard			
			No.	03-13	03-14	03-15	04-01	04-02	04-03	04-04	04-05	05-01	05-05											
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now		
Check one	TSI																							
	Surfacing																							
	Miscellaneous		X		X		X		X		X		X		X		X		X					
	Assumed ACBM		X	X	X	X	X	X	X	X			X	X	X	X	X	X	X	X	X			
	Sampled/Tested										X													
	Non ACBM										X													
	ACBM																							
	Nonfriable		X	X	X	X	X	X	X	X	X		X	X	X	X	X	X	X	X	X			
Friable																								
Assessment/Reassessment																								
Change in Condition? (Y/N)			N		N		N		Y		N		N		Y		Y		N		N			
Rate 1 To 5 5 is Worst	Deterioration								Removed Or Covered W/ New Ceramic Floor Tile.						Most Covered W/ New Ceramic Floor Tile.						Most Covered W/ New Ceramic Floor Tile.			
	Physical Damage																							
	Water Damage																							
	Activity/Vibration																							
	Exposure																							
Length of Exposure	Accessibility																							
	1 Hour/Week																							
	5 Hours/Week																							
	10 Hours/Week																							
	20 Hours/Week																							
Check All That Apply	40 Hours/Week																							
	Maintenance																							
	Custodial																							
	Faculty/Students																							
	Public																							
	Assessment Category																							

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-11-18										Date Of Reinspection – 11-16-21												
LEA Name – Marshal County Schools										LEA # 048												
School Name – Marshall County Tech School										School # 600												
Building Name - Main										Building # 01												
Address: 12312 US Hwy. 431 S. Guntersville, Alabama 35976										Inspector's Name – Drew Patrick												
										Signature - <i>Drew Patrick</i>												
										Alabama Accreditation No. – AIN10212B48EAD0												
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	400 sq. ft. Wallboard		2500 sq. ft. Decking		5000 sq. ft. Decking		2500 sq. ft. Decking		2600 sq. ft. Decking		38500 sq. ft. Decking		120 sq. ft. Transite Ceiling Tile		120 sq. ft. Transite Ceiling Tile		2045 sq. ft. Plaster		Pipe Elbow Insulation (Boiler Room)	
		No.	06-04	07-14	07-15	07-16	07-17	07-21	08-18	08-19	09-20	10-21										
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					X
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X			
	Assumed ACBM		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X		
	Sampled/Tested																				X	
	Non ACBM																				X	X
	ACBM																					
	Nonfriable		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X		
Friable																				X	X	
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						

**Alabama Asbestos Management Program
AHERA Reinspection Form**

Date of Previous Inspection – 12-11-18						Date Of Reinspection – 11-16-21					
LEA Name – Marshal County Schools						LEA # 048					
School Name – Marshall County Tech School						School # 600					
Building Name - Mechanical Shops						Building # 02					
Address: 12312 US Hwy. 431 S. Guntersville, Alabama 35976						Inspector's Name – Drew Patrick					
						Signature - <i>Drew Patrick</i>					
						Alabama Accreditation No. – AIN10212B48EAD0					

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	575 sq. ft. Ceiling Tile	50 sq. ft. Ceiling Tile	1060 sq. ft. Ceiling Tile	575 sq. ft. Ceiling Tile	575 sq. ft. Floor Tile	50 sq. ft. Floor Tile	1060 sq. ft. Floor Tile	60 sq. ft. Transite Panels	18,000 sq. ft. Decking	1230 sq. ft. Plaster
		No.	01-01	01-02	01-04	01-05	02-01	02-02	02-04	03-03	04-03	05-06

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
-------------------------	--	-------	-----	-------	-----	-------	-----	-------	-----	-------	-----	-------	-----	-------	-----	-------	-----

Check one	TSI																
	Surfacing																X
	Miscellaneous	X		X		X		X		X		X		X		X	
	Assumed ACBM	X		X		X		X		X		X		X	X	X	X
	Sampled/Tested																
	Non ACBM																
	ACBM																
	Nonfriable	X		X		X		X		X		X		X	X	X	X
Friable																	

Assessment/Reassessment																	
-------------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

Change in Condition? (Y/N)		N	N	N	N	N	N	N	N	N	N	N	N
----------------------------	--	---	---	---	---	---	---	---	---	---	---	---	---

Rate 1 To 5 5 is Worst	Deterioration	Replaced W/ New Ceiling Tile.	Replaced W/ New Ceiling Tile.	Replaced W/ New Ceiling Tile.	Replaced W/ New Ceiling Tile.	Replaced W/ New 12" Floor Tile.	Replaced W/ New 12" Floor Tile.	Replaced W/ New 12" Floor Tile.	Determined To Be Masonite Window Panels.								
	Physical Damage																
	Water Damage																
	Activity/Vibration																
	Exposure																
Length of Exposure	Accessibility	Replaced W/ New Ceiling Tile.	Replaced W/ New Ceiling Tile.	Replaced W/ New Ceiling Tile.	Replaced W/ New Ceiling Tile.	Replaced W/ New 12" Floor Tile.	Replaced W/ New 12" Floor Tile.	Replaced W/ New 12" Floor Tile.	Determined To Be Masonite Window Panels.								
	1 Hour/Week																
	5 Hours/Week																
	10 Hours/Week																
	20 Hours/Week																
Check All That Apply	Maintenance	Replaced W/ New Ceiling Tile.	Replaced W/ New Ceiling Tile.	Replaced W/ New Ceiling Tile.	Replaced W/ New Ceiling Tile.	Replaced W/ New 12" Floor Tile.	Replaced W/ New 12" Floor Tile.	Replaced W/ New 12" Floor Tile.	Determined To Be Masonite Window Panels.								
	Custodial																
	Faculty/Students																
	Public																
	Assessment Category																